



APPENDIX C

Site Photographic Record



APPENDIX C

Site Photographic Record. (Selected Photos) – Durham–York Energy Centre Surface Water Monitoring Program – During Construction Year 3



Photograph 1: View of E-SWMP looking south on April 30, 2014



Photograph 2: View of E-SWMP-outlet looking south on April 30, 2014



Photograph 3: View of W-SWMP looking south on April 30, 2014



Photograph 4: View of SW1 looking east on April 30, 2014



Photograph 5: View of SW2 looking south on April 30, 2014



Photograph 6: View of SW3 looking southwest on April 30, 2014



APPENDIX C

Site Photographic Record. (Selected Photos) – Durham–York Energy Centre Surface Water Monitoring Program – During Construction Year 3



Photograph 7: View of SW4 looking northwest on April 30, 2014



Photograph 8: View of E-SWMP outlet looking south on May 30, 2014



Photograph 9: View of SW1 looking east on May 30, 2014



Photograph 10: View of E-SWMP-outlet looking south on May 30, 2014



Photograph 11: View of W-SWMP-outlet on July 28, 2014



Photograph 12: View of SW3 looking north on May 30, 2014



APPENDIX C

Site Photographic Record. (Selected Photos) – Durham–York Energy Centre Surface Water Monitoring Program – During Construction Year 3



Photograph 13: View of W-SWMP looking west on May 30, 2014



Photograph 14: View of E-SWMP looking south on May 30, 2014



Photograph 15: View of E-SWMP looking south on June 17, 2014



Photograph 16: View of E-SWMP looking south on July 25, 2014



Photograph 17: View of W-SWMP looking west on July 25, 2014



Photograph 18: View of W-SWMP looking east on July 25, 2014



APPENDIX C

Site Photographic Record. (Selected Photos) – Durham–York Energy Centre Surface Water Monitoring Program – During Construction Year 3



Photograph 19: View of SW1 looking east on September 11, 2014



Photograph 20: View of W-SWMP looking west on September 11, 2014



Photograph 21: View of SW3 looking south on September 11, 2014



Photograph 22: View of SW4 looking west on September 11, 2014



Photograph 23: View of W-SWMP-outlet on September 11, 2014



Photograph 24: View of SW1 looking south on October 24, 2014



APPENDIX C


Site Photographic Record. (Selected Photos) – Durham–York Energy Centre Surface Water Monitoring Program – During Construction Year 3



Photograph 25: View of SW2 looking south on October 24, 2014



Photograph 26: View of W-SWMP looking west on October 24, 2014



Photograph 27: View of SW1 looking south on October 24, 2014



Photograph 28: View of W-SWMP-outlet on September 11, 2014



Photograph 29: View of sump-like conditions below frac tank looking north November 12, 2014



Photograph 30: View between main entrance and the plant November 12, 2014



APPENDIX C

Site Photographic Record. (Selected Photos) – Durham–York Energy Centre Surface Water Monitoring Program – During Construction Year 3



Photograph 31: View of east side of the plant facing south November 12, 2014



Photograph 32: View of two transformers and their respective containment areas November 12, 2014



Photograph 33: View of west side of the plant November 12, 2014



Photograph 34: View of two transformers and their respective containment areas November 12, 2014